

# Grandfather's House



A closer look will let you see that this 2-storey house was structured around a framework of upright rough-cut branches which extended from the ground up to the top of the second floor. The ridge itself is of corrugated iron sheeting but a considerable amount of the thatch has slipped down from the ridge.

The entire building is in very unstable condition at the moment (November 2007) . I imagine that in another year the roof will be gone completely – so too will the evidence of the 2-storey wooden (large branches or young trees) uprights around which the mud walls of this high building were constructed.

